



### NOTE:

With the rain water outlet at slab level and loose laid insulation and tiles, rain water will drain away through the foam and tile joints. The light weight foam concrete to falls which always causes problems from a waterproofing point of view can be omitted. The Baytec membrane is suitable for permanent immersion in water and will not be affected by the very small volume of standing water in the overlay joints, this will evaporate in a very short period of time.

SKETCH: TYPICAL FLAST ROOF DETAIL

For further information regarding this diagram please contact:

Pitchmastic PmB Limited



A Division of Pitchmastic PmB Ltd

Panama House, 184 Attercliffe Road, Sheffield, S4 7WZ

T: +44 (0) 114 270 0100

F: +44 (0) 114 276 882

E: [info@pitchmasticpmb.co.uk](mailto:info@pitchmasticpmb.co.uk)